

DRAFT - DISCHARGE UPDATE REPORT

Project: Temple-Inland Bogalusa Mill
Project Location: Bogalusa, Louisiana
Report Prepared By: Ed Cote
Date: September 1, 2011

Status of Report: Complete as of 4:00 PM, September 1 pending additional sampling and analyses

Weather Conditions: AM: fair/sunny PM: fair/sunny
Temperature: Max. 92°F
Cloud Cover: (Yes) (No)
Precipitation: (Yes) (No)

Discharge:
Beginning Time: Continuous
Ending Time: _____
Discharge Stoppage: No

Reason for Stoppage:
Description:

Activities, Remarks:

- Discharged all day between 6 and 12 MGD.
- Outfall monitoring was conducted in accordance with approved plan
- pH of discharge was within acceptable range
- ARCADIS assisted Temple-Inland with weir adjustments to maintain target flow

Problems/Deficiencies/Corrective Actions:

- pH meter with new probe at Outfall 001 had erroneous readings due to turbulence in sewer. The new design is being installed to provide a quiescent location.

Samples Taken / Results:

- Samples collected per frequencies indicated in Table 1 of approved Discharge Plan and results (to time indicated in above status) presented in attached table.

Calibration Records on Field Testing Equipment

- Outfall online pH and conductivity meters calibrated by Temple-Inland
- EBS sampling meters calibrated prior to start of discharge

Oversight/Visitors

- LDEQ representatives on site
- ISCO flow meter vendor representative
- EBS Sampling Laboratory